

Safety Issue Type: Recalls

March 18 2020 NHTSA Campaign Number: 20V151000

Doors May Not Open From The Inside

If a door cannot be opened with the interior handle in the case of an emergency, it can increase the risk of injury for the driver or passenger.

NHTSA Campaign Number 20V151000

Manufacturer Lamborghini (Automobili Lamborghini)

Components STRUCTURE

Potential Number of Units Affected 26

Summary

Lamborghini (Automobili Lamborghini) is recalling certain 2020 Aventador SVJ Coupe and Aventador SVJ Roadster vehicles. The interior door handle mechanism may fail, resulting in the vehicle's door being unable to be opened by using the inside door handle.

Remedy

Lamborghini will notify owners, and dealers will replace the interior door handle, free of charge. The recall is expected to begin May 1, 2020. Owners may contact Lamborghini customer service at 1-866-681-6276. Lamborghini's number for this recall is L73X-R.02.20.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Affected Products (2)

Vehicle

MAKE	MODEL	YEAR
LAMBORGHINI	AVENTADOR ROADSTER	2020
LAMBORGHINI	AVENTADOR SVJ	2020

Associated Documents (2)

Defect Notice 573 Report

RCLRPT-20V151-3554.PDF 214.561KB

<https://static.nhtsa.gov/odi/rcl/2020/RCLRPT-20V151-3554.PDF>

Recall Acknowledgement

RCAK-20V151-1886.pdf 245.605KB

<https://static.nhtsa.gov/odi/rcl/2020/RCAK-20V151-1886.pdf>